



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1950

Work Order Type: Weatherization

Audit Name: 14014SO1950

CLIENT INFORMATION

Client Name:

Address:

Client ID: 14014SO1950

TULLAHOMA, TN 37388

Alt. Client ID: MOORE

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY

Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY
FAYETTEVILLE, TN 37334-2001

Fax: (931) 438-0074

Email Address: e.satterfield@schra.us

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: 14014SO1950

Alt. Client ID: MOORE

Work Order (Bid Form)

Work Order Name: 14014SO1950

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 6

Measures

Measure 1 Infiltration Redctn

Components

Inspected

- Comment** 1. SEAL DUCT WORK / INTERIOR AIR SEAL - PLUMBING AND ELECTRICAL
2. INSULATE ATTIC ACCESS WITH BLUE BOARD AND ADD LATCHES
3. W/S AND D/S KITCHEN DOOR - TO UTILITY ROOM

☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------------|------------------------|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Miscellaneous Supplies | Infiltration Reduction | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Labor | LABOR | Hour | | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 Replace Htg. System

Components HS1

Inspected

- Comment** INSTALL NEW SPLIT UNIT

☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|-------------------|-----------------------|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Heating Equipment | Replacement HVAC | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Labor | LABOR | Hour | | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 14014SO1950

Alt. Client ID: MOORE

Work Order (Bid Form)

Work Order Name: 14014SO1950

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 6

Measure 3 Window Sealing**Components****Inspected****Comment** CAULK ALL WINDOWS☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|-----------------------|-------------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Windows | Window Sealing | Each Window | 14 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Labor | Window Sealing | Each Window | 14 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 Attic Ins. R-30****Components****Inspected****Comment**☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|---|-------|------|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Insulation | Attic Insulation - Blown Cellulose - R-30 | SqFt | 1260 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Labor | Attic Insulation - Blown Cellulose - R-30 | SqFt | 1260 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO1950

Alt. Client ID: MOORE

Work Order (Bid Form)

Work Order Name: 14014SO1950

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 6

| Measure 5 DWH Pipe Insulation | | | | Components | | | | Inspected | |
|-------------------------------|------------------|-----------------------|-------|------------|-----------|--------|------------|-----------|-------|
| Comment | | | | | | | | | |
| | | | | Estimated | | Actual | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Insulation | DHW Pipe Insulation | Each | 1 | | | | | |
| 2 | Labor | DHW Pipe Insulation | Each | 1 | | | | | |
| Other Detail | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Measure Sub Total: | | | | | | | Sub Total: | | |
| Field Notes: | | | | | | | | | |

| Measure 6 DWH Tank Insulation | | | | Components | | | | Inspected | |
|-------------------------------|---------------------|-----------------------|-------|------------|-----------|--------|------------|-----------|-------|
| Comment | | | | | | | | | |
| | | | | Estimated | | Actual | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Hot Water Equipment | DHW Tank Insulation | Each | 1 | | | | | |
| 2 | Labor | DHW Tank Insulation | Each | 1 | | | | | |
| Other Detail | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Measure Sub Total: | | | | | | | Sub Total: | | |
| Field Notes: | | | | | | | | | |

| Measure 7 Fix Improper Venting (Clothes Dryer) | | | | Components | | | | Inspected | |
|---|-------------------------|-----------------------|-------|-------------------|-----------|---------------|-------------------|------------------|-------|
| Comment | | | | | | | | | |
| | | | | Estimated | | Actual | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Metal Flex | Each | 1 | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | |
| Other Detail | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Measure Sub Total: | | | | | | | Sub Total: | | |
| Field Notes: | | | | | | | | | |

| Measure 8 PressureRelief Piping Needed | | | | Components | | | | Inspected | |
|---|-------------------------|------------------------|-------|-------------------|-----------|---------------|-------------------|------------------|-------|
| Comment | | | | | | | | | |
| | | | | Estimated | | Actual | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Pressure relief piping | Each | 1 | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | |
| Other Detail | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Measure Sub Total: | | | | | | | Sub Total: | | |
| Field Notes: | | | | | | | | | |

Measure 9 Smoke Detector is Needed**Components****Inspected****Comment**

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|-------------------------|-------------------------|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Smoke / Carbon detector | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Labor | Labor | Hour | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 14014SO1950

Alt. Client ID: MOORE

Work Order (Bid Form)

Work Order Name: 14014SO1950

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 6 of 6